## **Under Review Notification**

Raised By: Vanessa Morel Product #: RBW109-3400-95-1

Date: 2019.10.27 Product Name: 90° GEARBOX OUTPUT SHAFT SEAL REMOVAL AS

		"Y" or "N" Required for Each Part							t		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBW109-3400-95-1	RBW109-3400-95-1 Rev	Υ	Υ	Ν	Υ	Υ	Ν	N	N	19-988	See below

## **Description of Issue:**

Issues stated on ADR (Fit issues, Manufacturing issue)

RBW109-3400-95-1 and items -1, -3, -5, -7, -9, -11, -13, -15, -23, -25 and -29 must be put on **HOLD** in Plex

RBW109-3400-95-1 Finish good stock can be use as is

Items -1, -3, -5, -7, -9, -11, -13, -15, -23, -25 and -29 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: Director of Engineering **VP** Operations Customer Support Manager **Technical Support Director of Operations** Chief Engineer **Production Engineers** Product Manager - Solutions Provider **Engineering Project Managers Production Planners** Supply Chain Director / Senior Buyer **Director Quality Assurance** QC Coordinator **Engineering Clerk Purchasing Manager** Marketing Eugene